



Stanislaus Consolidated Fire Protection District  
3324 Topeka St.  
Riverbank, CA 95367  
(209) 869-7470  
(209) 869-7475

## **Recommendations for Replacement of Missing Fire Department Connections (FDCs)**

- FDCs may be tacked (brazed) in place.
- The use of lock-tight may be used.
- If a set-screw is used, the set-screw may be brazed over so the set-screw has to be drilled out.
- Iron instead of brass may be used.
- Consider the use of locking devices. Specific locking devices cannot be recommended but a search of the internet may be of assistance. Try searching FDC Locking Devices.
- Please notify the Fire District of locking device type when/if installed.

**Missing or damaged connections must be repaired/replaced as soon as possible.**